## Approved For Release 2001/03/02 : CIA-RDP78-04993A000100060002-0

		25X 1A68
	VIA R CONFIDENTIAL' I	DISPATCH NO.
	SECRET	8 <b>!</b> NOV 1957
	TO : Chief, FE DATE	
	ATTN: RE&C,OL FROM: Chief,	25X1A6a
	SUBJECT { GENERAL - Support/Administrative   SPECIFIC - Dehumidified Warehouse - Building #1.	104
: .	ACTION REQUIRED: For information only	
		25X1A
5X1A	1. Prior to his departure from Headquarters, the was requested by RE&C D	ivision representatives
	to submit certain information concerning the dehumid: Building #1104. This information is as follows:	ified warehouse, 7. C/REC
. 4	a. Normal humidity maintained?	DC/REC_
	44%	C/ACQ
		, C/C.E.
	b. Number of units installed?	1. C/U.E. J. WA(1)2
	One	REPORT
	c. Catalog No. of unit?	
•	DOR 1050 - Desomatic Products Inc.	aka
	d. Number of units required for normal ope	ration?
	One	FILE (return)-
	e. Average or approximate time required to to normal operating conditions?	an of
	Warehouse contents and high outside hum prohibit on-off operation. The unit is in constant	
	ument No. 12 f. Per	riod of regeneration/
- \ _	Declassified CUNFIDENTIAL	RECORDED
Class   Auth	s. Changed To: TS SC SECRET	OL REGISTRY
Date	11 14060 A Eor Religa S 2001/03/02 : C/A-RDP78-0498	3A000100060002-0
***************************************	THE TOTAL STATE OF THE STATE OF	123-1-4

## Approved For Release 2001/03/02 : CIA-RDP78-04683A000100060002-0

SECRET

25X1A6a

5 November 1957 Page 2

8 NOV 1957.

- f. Period of regeneration for unit?70 minutes maximum capacity.
- g. Approximate power required for operation of unit? Connected full load is 34 K.W.
- h. Cost of installation?
  \$10,200 paid by contractor for the unit.
- i. Operating difficulties or problems?

Excellent results have been obtained with this unit. We have experienced no mechanical trouble. Maintenance is easily applied and minor electrical difficulties are our only problems.

j. Miscellaneous comments:

It is recommended that for future installations the unit be isolated from the general storage area by partitioning of grillwork, hardware cloth, etc. Adequate lighting (permanent wall fixtures) for servicing such units would be advantageous.

2. Additional information will be provided upon request.



25X1A9a

5 November 1957

Distribution:

2 - Chief, FE

3 - RE&C,OL

## CONFIDENTIAL